

European Specialty Automotive
 1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

2290

Org. Est. # 003102

Invoice from History

Work Completed : 04/14/2015

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 0

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Bulb - Multi Purpose - 12v 1157		1.00	1.60	1.60		
Bulb - Multi Purpose - 12V 5W 5007		1.00	2.56	2.56		
Light Bulb OES		1.00	2.48	2.48		
<p>[Recommendations] Perform Lube, Oil & Filter Exchange on 8/31/2020 or 138300 Kilometers.</p> <p>Recommend replacing the rear shocks, plus bump stop</p>						
Taxes						
GST						0.33
PST						0.46

Org. Estimate 7.44 Revisions 0.00 Current Estimate 7.44

Labor:	0.00
Parts:	6.64
SubTotal:	6.64
Tax:	0.80
Total:	7.44
Bal Due:	\$0.00

[Payments - Visa - \$7.44]

Vehicle Received: 4/14/2015

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

Service Advisor : CH, Tech :

Invoice from History

Work Completed : 01/01/-4713

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 101074

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Intermed. Shaft Brg. Set Single Row Bearing 106-08.2		1.00	1,131.62	1,131.62	FLYWHEEL (STD TRANS) - Remove & Reinstall - Carrera 4S - [Includes: R&I engine where necessary.]	1,067.00
Crankshaft Seal 997 101 212 01		1.00	43.40	43.40	Additional time to replace IMS	220.00
Flywheel Bolt 999 073 092 02		8.00	4.08	32.64	Inspect exhaust system for rust/damage	n/c
Driveshaft Flex Joint 997 421 020 00		1.00	129.66	129.66	Stage 2/3 Cut Polish	200.00
Door Lock 8N1 837 015C		1.00	233.51	233.51	Repair RR brake light. Bulb has been replaced many times.	n/c
Full Synthetic Porsche Spec Engine Oil. 5W40		8.50	10.95	93.08	DOOR LOCK ACTUATOR / SOLENOID - Remove & Replace - Drivers Door	143.00
Oil Filter 930 107 764 01		1.00	19.95	19.95	Hazardous Materials	8.00
Shop Supplies				40.00		
						GST 168.09
						PST 235.33

Org. Estimate 13.44 Revisions 3,445.53 Current Estimate 3,458.97

Labor:	1,630.00
Parts:	1,723.86
HazMat:	8.00
SubTotal:	3,361.86
Tax:	403.42
Total:	3,765.28
Bal Due:	\$0.00

Vehicle Received: 1/1/-4713

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2

Phone: 250-758-3288

Thank You For Supporting Local Business

INVOICE

7164

Invoice from History

Work Completed : 04/20/2018

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 121729

Odometer Out : 121735

VIN # : WPOCA299X 4S652707

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Jectron-Fuel System Cleaner LM7711	1.00	10.90	10.90	Oil Service	88.00
Full Synthetic LIQUIMOLY OE Spec Engine Oil BULKOIL	8.50	10.95	93.08	Change engine oil and engine oil filter. Check operation of all exterior lights. Evaluate all fluid levels for proper level and condition. Inspect belts and hoses. Lubricate door locks, door seals, linkages, door hinges and power antenna (if applicable). Visually inspect undercarriage, tires and battery. Road test to check for any possible drivability issues.	
OIL FILTER Size: CN: E14HD77 OX128/1D	1.00	26.95	26.95	Hazardous Materials	8.00
Shop Supplies			4.00		
					GST 11.55
					PST 16.17

Org. Estimate 258.65 Revisions 0.00 Current Estimate 258.65

Labor:	88.00
Parts:	134.93
HazMat:	8.00
SubTotal:	230.93
Tax:	27.72
Total:	258.65
Bal Due:	\$0.00

[Payments - Visa - \$258.65]

Vehicle Received: 4/20/2018

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

European Specialty Automotive
 1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

9370

Invoice from History

Work Completed : 05/30/2019 **Date: 05/07/2021**

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
 Lic # : 627MPP Odometer In : 126089

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Daytime Light Relay		1.00	175.31	175.31	confirm fault with ABS	120.00
996 615 111 00					No fault found with wheel speed sensors. Fault found with brake switch A circuit. Checked tail lights and found right tail light inoperative. Checked tail lights with light switch on and all lights work. DRL relay faulty causing only left lights to come on with vehicle running but all lights work when switch turned on. Recommend replacing DRL relay	
Shop Supplies				4.00	DAYTIME RUNNING LAMPS RELAY - Remove & Replace - All Applicable Models	n/c
					replaced DRL relay, confirmed proper operation of lights	
						GST 14.97
						PST 20.95

Org. Estimate 12.00 Revisions 666.52 Current Estimate 678.52

Labor:	120.00
Parts:	179.31
SubTotal:	299.31
Tax:	35.92
Total:	335.23
Bal Due:	\$0.00

[Payments - Visa - \$335.23]
 Vehicle Received: 5/30/2019

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

Invoice from History

Work Completed : 07/29/2015

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 101597

VIN # : WPOCA299X 4S652707

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Tail Lamp Socket/Pigtail assembly <i>Tail Lamp Socket</i>	1.00	65.80	65.80	MUFFLER - Remove & Replace - One Side	176.00
Muffler Right Side <i>Muffler</i>	1.00	1,525.00	1,525.00	TAIL LAMP HARNESS- Remove & Replace - Convertible Right Side	55.00
Muffler Clamp <i>clamp</i>	1.00	53.95	53.95	Replace one spark plug beside muffler. Customer supplied part.	22.00
Freight <i>Freight</i>	1.00	30.00	30.00	Additional Time to unseize exhaust bolts and drill and use extractor to remove bolts as necessary.	198.00
Nut <i>99950009200</i>	3.00	5.32	15.96	Hazardous Materials	8.00
Shop Supplies			40.00		
					GST 109.49
					PST 153.28

Org. Estimate 13.44 Revisions 2,140.90 Current Estimate 2,154.34

Labor:	451.00
Parts:	1,730.71
HazMat:	8.00
SubTotal:	2,189.71
Tax:	262.77
Total:	2,452.48
Bal Due:	\$0.00

[Payments - Cash - \$2,452.48]

Vehicle Received: 7/29/2015

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

3907

Org. Est. # 004818

Invoice from History

Work Completed : 05/18/2016

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 107228

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Battery - 640CCA - 80 Amp Hour S5572B		1.00	248.68	248.68	Right brake light still not working. Lamp harness was replaced.	n/c
Heater Core 997 572 129 00		1.00	423.84	423.84	Check all lights, all lights working at this time.	
Coolant A/F		2.00	21.78	43.56	Inspect for cause of exhaust noise. Right side muffler was replaced.	55.00
Shop Supplies				11.55	Extract 2 rusted exhaust clamp bolts and replace bolts. Also found rocks in under tray that was touching oil pan and causing rattle noise, Remove rocks and adjust belly pan.	
					Diagnose Coolant Smell in Cabin	55.00
					Diagnose Starter Issue	55.00
					BATTERY - Remove & Replace - All Applicable Models - [Includes: Test.]	77.00
					HEATER CORE - Remove & Replace - All Applicable Models -	220.00
					Hazardous Materials	8.00
					GST	59.88
					PST	83.83

Org. Estimate 236.27 Revisions 1,284.54 Current Estimate 1,520.81

Labor:	462.00
Parts:	727.63
HazMat:	8.00
SubTotal:	1,197.63
Tax:	143.71
Total:	1,341.34
Bal Due:	\$0.00

[Payments - Debit - \$1,341.34]

Vehicle Received: 5/18/2016

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

4123

Org. Est. # 005607

Invoice from History

Work Completed : 06/28/2016

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 108122

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Coolant/Antifreeze - 1.5 Liters (Pink) G 013 A8J M1		3.00	26.20	78.60	ALTERNATOR DRIVE BELT - Remove & Replace - Normally Aspirated - [Includes: Serpentine type Belt(s.)]	66.00
Water Pump - w/ Gasket 996 106 011 56		1.00	400.50	400.50	ALTERNATOR DRIVE BELT - Remove & Replace - Normally Aspirated - [Includes: Serpentine type Belt(s.)]	-66.00
Thermostat 996 106 125 53		1.00	107.86	107.86	Diagnose Coolant Leak. Lost all coolant.	33.00
Drive Belt 6PK-2115		1.00	62.68	62.68	THERMOSTAT - Remove & Replace - Carrera 4S - [DOES NOT include bleed Cooling System.]	143.00
Shop Supplies				13.75	WATER PUMP - Remove & Replace - Carrera 4S - Includes bleed Cooling System.]	374.00
					Hazardous Materials	8.00
						GST 61.07
						PST 85.50

Org. Estimate 1,367.96 Revisions 0.00 Current Estimate 1,367.96

Labor:	550.00
Parts:	663.39
HazMat:	8.00
SubTotal:	1,221.39
Tax:	146.57
Total:	1,367.96
Bal Due:	\$0.00

[Payments - Cash - \$1,100.00, Visa - \$267.96]

Vehicle Received: 6/28/2016

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

4643

Org. Est. # 006232

Invoice from History

Work Completed : 10/26/2016

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 110443

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Jectron LM4007		1.00	13.75	13.75	Oil Service	88.00
Full synthetic porsche spec engine oil 5/40		8.80	10.95	96.36	Carry out servicing. Change oil and filter; check lights and levels; check belts and hoses; lube door locks, seals, hinges and weather strips. Visually inspect undercarriage, tires, brakes and battery. Check antifreeze good to -	
OIL FILTER Size: CN: E14HD77 OX128/1D		1.00	26.95	26.95	Inspect exhaust system for noise. Starts after car has been driven to operating temp and shut off for about 10 min, then driven again. It only happens on decel. This is the third visit for the same complaint.	n/c
Shop Supplies				4.00	Hazardous Materials	8.00
						GST 11.85
						PST 16.59

Org. Estimate 265.50 Revisions 0.00 Current Estimate 265.50

Labor:	88.00
Parts:	141.06
HazMat:	8.00
SubTotal:	237.06
Tax:	28.44
Total:	265.50
Bal Due:	\$0.00

[Payments - Visa - \$265.50]

Vehicle Received: 10/26/2016

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

6715

Org. Est. # 008582

Invoice from History

Work Completed : 01/12/2018

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 120108

VIN # : WPOCA299X 4S652707

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext				
Bosch Wiper Blade Size: 22" 40722A		2.00	22.76	45.52	Keyless entry functions not working on either remote - check and advise Checked faults and checked live data, not seeing either key, swap cover and battery to make one key, works. Put new key head on other blade and program. Ok	69.95				
Shop Supplies				4.00						
<table border="0"> <tr> <td>GST</td> <td>5.97</td> </tr> <tr> <td>PST</td> <td>8.36</td> </tr> </table>						GST	5.97	PST	8.36	
GST	5.97									
PST	8.36									

Org. Estimate 82.83 Revisions 0.00 Current Estimate 82.83

Labor:	69.95
Parts:	49.52
SubTotal:	119.47
Tax:	14.33
Total:	133.80
Bal Due:	\$0.00

[Payments - Visa - \$133.80]
 Vehicle Received: 1/12/2018

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

7779

Org. Est. # 009796

Invoice from History

Work Completed : 08/02/2018

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 123038

VIN # : WPOCA299X 4S652707

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
R134A Refrigerant (1KG) R134A	1.00	68.80	68.80	Perform AC Performance Test, Computer Scan (if applicable), Charge System. removed 540 grams, system holds 880 grams, system is fully charged injected system with dye to determine if any leaks are present R-134A 850g Dye/sealant Hazardous Materials	168.00
A/C Leak Stop / UV Dye 4oz SE9401	1.00	24.99	24.99		
Shop Supplies			4.20		8.00
					GST 13.70
					PST 19.18

Org. Estimate 306.87 Revisions 0.00 Current Estimate 306.87

Labor:	168.00
Parts:	97.99
HazMat:	8.00
SubTotal:	273.99
Tax:	32.88
Total:	306.87
Bal Due:	\$0.00

[Payments - Visa - \$306.87]

Vehicle Received: 8/2/2018

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Invoice from History

Work Completed : 10/05/2018

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 124040

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext	
Fuel Tank Cap		1.00	33.78	33.78	Diagnostic Computer Scan - diagnose check engine or other malfunction indicator lights. (Extra diagnostic time may be required for issues with more complex diagnostic procedures) DME code for EVAP system small leak has been cleared. Component activation for secondary air and EVAP system has been performed and passed. Fuel cap in poor condition. Suggest replacement of cap. If faults reoccur further in-depth diagnostic will be required	69.95	
996 201 241 03							
Shop Supplies				4.00			
						GST	5.39
						PST	7.54

Org. Estimate 120.66 Revisions 0.00 Current Estimate 120.66

Labor:	69.95
Parts:	37.78
SubTotal:	107.73
Tax:	12.93
Total:	120.66
Bal Due:	\$0.00

[Payments - Debit - \$120.66]
 Vehicle Received: 10/5/2018

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288

Thank You For Supporting Local Business

INVOICE

9045

Org. Est. # 011249

Invoice from History

Work Completed : 03/27/2019

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 124726

Odometer Out : 124732

VIN # : WP0CA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
FABSPEED SuperCup Performance Muffler Kit <i>SPECIAL</i>		1.00	2,951.45	2,951.45	BROKERAGE/CUSTOMS	287.45
Alternator 120 Amp <i>AL 0812 X</i>		1.00	825.27	825.27	Install FABSPEED Exhaust System. Reassemble/Install Bumper Assy	300.00
Wholesale price adjustment <i>WholeSale</i>		1.00	-164.84	-164.84	Removed old exhaust to install aftermarket mufflers. Adjusted fitting and installed bumper.	
Shop Supplies				19.61	Initial road test (OK). Cold start (OK). 3rd start-Road test (Battery light)	24.00
					Scanned and cleared codes. Checked fuses and connection at alternator. Recommend new alternator	196.80
					ALTERNATOR ASSEMBLY - Remove & Replace - Carrera 4S Removed and replaced alternator.	156.00
					GOODWILL LABOR ADJUSTMENT	-180.00
						GST 220.79
						PST 309.10

Org. Estimate 4,650.10 Revisions 0.00 Current Estimate 4,650.10

Labor:	496.80
Parts:	3,631.49
Sublet:	287.45
SubTotal:	4,415.74
Tax:	529.89
Total:	4,945.63
Bal Due:	\$0.00

[Payments - Check (#Customer Credit) - \$1,588.58, Applied Credits - \$3,357.05]

Vehicle Received: 3/21/2019

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com

European Specialty Automotive

1702 Northfield Road
 Nanaimo, BC. V9S3B2
 Phone: 250-758-3288
 Thank You For Supporting Local Business

INVOICE

9147

Org. Est. # 011368

Invoice from History

Work Completed : 04/25/2019

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)

Lic # : 627MPP

Odometer In : 125471

VIN # : WPOCA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Cable Loom 996-631-447-01		1.00	293.69	293.69	Replace right rear tail light wiring harness and verify proper operation,.	36.00
Cable Loom Parts discount 996-631-447-01		1.00	-293.69	-293.69	Removed and replaced right tail harness, tested and found new harness faulty. Diagnosed fault and repaired, bad connection found for brake light. Retested all lights working at this time.	
Tail Light Bulb **N-562** N562		1.00	1.99	1.99	Diagnostic Computer Scan - diagnose check engine or other malfunction requiring computer hook up/module reading. (Extra diagnostic time may be required for issues with more complex diagnostic procedures)	69.95
Oil Filler Tube 997 107 131 00		1.00	92.54	92.54	Oil fill neck split causing air leak and misfire. New oil fill neck needed before further diagnostics are done.	
Shop Supplies				4.15	Replace Oil filler tube as required.	60.00
					Re and re air filter assembly, throttle body assembly, accessory belt and alternator. Replace oil filler tube.	
						GST 13.23
						PST 18.52

Org. Estimate 521.67 Revisions 342.76 Current Estimate 864.43

Revision # 1, Previous Estimate Amount: 521.67, Additional Cost: 342.76, Revised Estimate: 864.43, Parts: \$302.04 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$40.72 Authorized by - Hawkins, Evan, Date - 4/23/2019, Time - 11:02 AM, Initiated By - Shop

Labor:	165.95
Parts:	98.68
SubTotal:	264.63
Tax:	31.75
Total:	296.38
Bal Due:	\$0.00

[Payments - Debit - \$296.38]
 Vehicle Received: 4/25/2019

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

European Specialty Automotive

1702 Northfield Road
Nanaimo, BC. V9S3B2

Phone: 250-758-3288

Thank You For Supporting Local Business

INVOICE

10123

Invoice from History

Work Completed : 08/30/2019

Date: 05/07/2021

2004 Porsche - 911 Carrera 4S - 3.6L, H6 (220Cl) VIN(A)

Lic # : 627MPP

Odometer In : 128258

Odometer Out : 128260

VIN # : WP0CA299X 4S652707

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
Jectron-Fuel System Cleaner LM7711		1.00	14.04	14.04	European Specialty Service Inspection: https://2un.me/p5h7yvq3	
Full Synthetic LIQUIMOLY OE Spec Engine Oil BULK OIL		8.80	10.95	96.36	NOTES: Front Brakes Measure at around 8mm Rear Brake Measurement at around 10mm	
OIL FILTER **OX128/1D** Size: CN: E14HD77 996 107 225 53		1.00	26.95	26.95	Tire Tread Depth (6/ 32nds) [Confirmed] Oil Service 8 am drop off will leave till lunch or wait	
Fuchs Maintain Fricofon Coolant 5L Size: PER 1 L G13		1.00	7.23	7.23	Oil Service	96.00
Shop Supplies				4.00	Change engine oil and engine oil filter. Check operation of all exterior lights. Evaluate all fluid levels for proper level and condition. Inspect belts and hoses. Visually inspect undercarriage, tires and battery. Road test to check for any possible drivability issues.	
					Oil service done CHECK CAPACITY.. 8.8L Coolant low added 1L	
					Hazardous Materials	8.00
					GST	12.63
					PST	17.68

Org. Estimate 282.89 Revisions 0.00 Current Estimate 282.89

Labor:	96.00
Parts:	148.58
HazMat:	8.00
SubTotal:	252.58
Tax:	30.31
Total:	282.89
Bal Due:	\$0.00

[Payments - Visa - \$282.89]

Vehicle Received: 8/30/2019

Customer Number : 1076

Warranty on parts and labor is one years or 20,000 KM whichever comes first. No warranty is expressed or implied if work is completed with customer supplied parts. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF YOUR WHEELS HAVE BEEN REMOVED AS A PART OF THE SERVICE THEY HAVE BEEN TORQUED TO FACTORY SPECIFICATIONS AND MUST BE RE TORQUED WITHIN 100-150 KM. Failure to do so could result in damage to your vehicle or injury.

Signature _____ Date _____

Visit us on the web: www.europeanspecialty.com

Email Address: service@europeanspecialty.com