

# Port Moody Auto & Air Repair Shop

89 Moray Street

Port Moody, B.C. V3H3M2

Phone: 604-461-7856 Fax: 604-461-7857

ICBC Vendor Mechanical Repair Facility #F168486

Sub Estimate

## Estimate for Services

Estimate Date : 23/11/2015

1975 Cadillac - Eldorado -  
Lic # : - B.C.

Odom. In: 0

VIN # : 6L47S5Q416143

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
WHEEL BEARING-RIGHT FRONT 6541354	1.00	215.76	215.76	WHEEL BEARING - Remove & Replace - FWD Front, Hub and Bearing, One Side - [Includes: Replace inner and outer bearings, cups and seals and repack where applicable. Includes: Replace seals and repack bearings where applicable.]	170.00
FRONT WHEEL SEAL-OUTER 32131-456840	1.00	34.84	34.84		
FRONT WHEEL SEAL-INNER 322135-85740	1.00	25.20	25.20	Hazardous Materials	5.56
Shop Supplies			8.75		

### [ Recommendations ]

Perform Lube, Oil & Filter Exchange on 19/02/2016 or 639900  
Kilometers.

Parts/Supplies: 284.55

Labor: 170.00

HazMat/Fees: 5.56

Tax: 55.22

Total : \$ 515.33

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. I hereby authorize an express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.