

Port Moody Auto & Air Repair Shop

89 Moray Street

Port Moody, B.C. V3H3M2

Phone: 604-461-7856 Fax: 604-461-7857

ICBC Vendor Mechanical Repair Facility #F168486

INVOICE

16333

Org. Est # 022776

INVOICE

Vehicle Received: **04/20/2016**

Invoice Date: **04/20/2016**

1975 Cadillac - Eldorado -

Lic # : - B.C.

Odometer In : 63621

VIN # : 6L47S5Q416143

Part Description	Qty	Sale	Ext	Labor Description	Extended
OIL FILTER	1.00	8.00	8.00	VIP 2-Change Engine Oil	n/c
Blended Motor Oil	5.00	4.50	22.50	Replace Oil Filter	
AC LINE-FABRICATED	1.00	175.00	175.00	lubricate chassis	
carb kit	1.00	65.00	65.00	ROTATE Tires	
THERMAL LIMITING SWITCH	1.00	15.76	15.76	40 Point Inspection	
Shop Supplies			8.75	Including Road Test	
				Written Report	
				**** Symptoms: ****	
				VIP2 Seasonal Maintenance Package-Labour Value 1 visit is 1	
				hourMUST BILL PARTS AND FLUIDS--	
				VIP 11-Refrigerant is additional charge by the calculated	n/c
				by the pound via ICBC rate	
				**** Symptoms: ****	
				Labour Free AC Recharge-	
				No fluid info available....	n/c
				**** Symptoms: ****	
				-	
				Change Motor Oil Lube Chassis	n/c
				Changed Motor Oil & Replaced Filter, Added 4 QTS Blended	
				Motor Oil, Lube Chassis, Check all Fluid Levels	
				The vent on driver side, near gas pedal is blowing hot air	n/c
				into the vehicle when heat is turned off.Please	
				diagnose.....	
				**** Symptoms: ****	
				-	
				The washer nozzel is not working,	n/c
				**** Symptoms: ****	
				-	
				While driving up hills , the engine will make a clunking	n/c
				sound, vehicle does not sputter but can hear the clunk.	
				**** Symptoms: ****	
				-	
				Has a gas smell in the vehicle, please diagnose.	n/c
				**** Symptoms: ****	
				-	
				DIAGNOSE FUEL SMELL/WASHER NOZEL/VENT	80.00
				BLOWING HOT AIR	
				CHECK CARB FOR FUEL LEAKS-CARB LEAKING IN MULTIPLE	
				SPOTS AND AT FUEL INLET-RECCOMEND TO REBUILD	
				CARB-INSPECT WASHER NOZLE-WASHER LINE IS	
				KINKED-REPAIR WASHER LINE AND NOW FUNCTIONS	
				PROPERLY-CHECK HVAC UNIT-HEATER FAN ALWAYS RUNS	
				EVEN THOUGH HEATER FAN SWITCH IS IN OFF	
				POSITION-HEATER FAN SWITCH IS NO GOOD AND	
				REQUIRES REPLACEMENT-ALL AFTERMARKET SWITCHES	
				ARE PART OF CLIMATE CONTROL UNIT	
				REMOVE AND REPLACE LOW SIDE AC	100.00
				LINE-EVAPORATOR TO CONDENSOR	
				CARBURETOR ASSEMBLY - Remove, Install, and	400.00
				Overhaul - All Applicable Models - [Includes: Install	
				carburetor kit, adjust idle speed and fuel mixture.]	

\$ 980⁰⁰ CASH
\$ 6.24 Debit.