

\$146.98

LESS

Alpina B7 4.4L  
7418

**SHIP TO**  
2011 BMW 750i Alpina B7  
4.4L WBAKC6C59BC447418

**INVOICE #** 2220  
**DATE** 17/01/2022  
**DUE DATE** 17/01/2022  
**TERMS** Due on receipt

ION

| SERVICE | QTY | RATE | AMOUNT |
|---------|-----|------|--------|
|---------|-----|------|--------|

|   |   |        |        |
|---|---|--------|--------|
| <b>Diagnosis /HR</b><br>Diagnose engine making a clicking noise - after long periods of driving | 1 | 119.99 | 119.99 |
|---|---|--------|--------|

Scanned vehicle - found no codes stored for engine malfunctions. Codes stored for transmission speed differentials but likely not the cause of the noise present  
 -Ran engine and checked visually and audibly for faults - none found

-Smoke tested crankcase and found that most of the PCV lines are leaking - this could cause a whistling noise under the correct circumstances  
 -Reccomend leaving car with us to road test or replacing the PCV lines and returning to customer to monitor noise

Subtotal: 119.99

|  |   |       |       |
|--|---|-------|-------|
|  | 1 | 19.99 | 19.99 |
|--|---|-------|-------|

**Shop Supplies**

Includes but not limited to: Lubricants, fluids, oil and chemical disposal, seals washers etc..

inspection:

- Engine oil leaks
- Thrust rod bushings worn
- LF axle leaking
- Front struts leaking
- Rear axle seal leak

|             |                   |
|-------------|-------------------|
| SUBTOTAL    | 139.98            |
| GST @ 5%    | 7.00              |
| TOTAL       | 146.98            |
| BALANCE DUE | <b>CAD 146.98</b> |

Thank you for your business.  
Referral is the best compliment that you can give

Signature \_\_\_\_\_