

Port Moody Auto & Air Repair Shop
 89 Moray Street
 Port Moody, B.C. V3H3M2
 Phone: 604-461-7856 Fax: 604-461-7857
 ICBC Vendor Mechanical Repair Facility #F168486
 Work Completed Date: 11/23/2015
 Vehicle Received: 11/23/2015

INVOICE

14743

Org. Est. # 020589

/2015
 #20589

INVOICE

WALLACE SUZAN

1975 Cadillac - Eldorado -
 Lic #: - B.C.

Odometer In : 63491

604-461-3910 HOMI 604-942-7000

VIN #: 6L47S5Q416143

Part Description	Qty	Sale	Ext	Labor Description	Extended
Fuel Additive	1.00	9.49	9.49	VIP1-Flush and replace Oil & Oil Filter	n/c
OIL FILTER	1.00	8.00	8.00	Fuel Additive	
Blended Motor Oil	5.00	4.50	22.50	Lubricate Chassis	
WIPER BLADE REFILL	2.00	15.44	30.88	Rotate Tires.	
Lite Bulb	1.00	15.00	15.00	40 Point Vehicle Inspection	
Shop Supplies			4.38	Road Test	
				With Written Report	
				**** Symptoms: ****	
				VIP1-Labour Value \$200	
				Billing Required for all FLUIDS and PARTS	n/c
				Booked In By Shelly	
				**** Symptoms: ****	
				Booked In By Shelly	n/c
				Oil Change Labour	
				**** Symptoms: ****	
				Oil Change	n/c
				DO NOT ROTATE TIRES---DO NOT ROAD TEST	
				**** Symptoms: ****	
				-----	n/c
				Booked In By Shelly	
				**** Symptoms: ****	
				Booked In By Shelly	n/c
				PLEASE NOTE Technicians findings:	
				RF turn signal is out	
				wipers streaky--will require refills for original s.steel frames	
				Right wheel bearing is loose	
				Engine oil leaks	
				**** Symptoms: ****	
				-----	30.00
				CLEAN AND ADJUST REAR BRAKES	
				REMOVE AND REPLACE WIPER BLADE REFILL	30.00
				Hazardous Materials	2.19

[Recommendations]

Perform Lube, Oil & Filter Exchange on 19/02/2016 or 639900 Kilometers.

Taxes	
GST	7.62
PST	10.67

