

CUSTOMER #: 56362

86308

Three Point Motors



Mercedes-Benz

INVOICE

2546 Government Street, Victoria, B.C. V8T 4P7
Tel: (250) 385-6737 Fax: (250) 385-2825
www.threepointmotors.com

8V8

PAGE 1

HOME: BUS: SERVICE ADVISOR: 90 STEVIE METCALFE

COLOUR	YEAR	MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
SIL	06	MERCEDES-BENZ CL600C	WDBPJ76J96A047730	468HHH	97091/97091	T9401	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST PAY LABOUR RATE	PAYMENT	INV. DATE
16JAN06 IS	16JAN06 DD	08DEC05	16JAN2010	17:00 30JUN23	169.00	CASH	28JUN23
R.O. OPENED	READY	OPTIONS: DLR:5915 ENG:5.5 Liter					
26JUN23	28JUN23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A REPLACE ABC LINE
 CAUSE: DIAGNOSTIC CHECK UP
 S13 ELECTRICAL / GENERAL DIAGNOSIS
 114 CP 676.00 676.00
 4 028-997-65-48 O RING 2.43 2.43 9.72
 1 220-320-59-72 OIL HIGH PRESSURE LINE 789.07 789.07 789.07
 4 001-989-24-03-09 HYDRAULIC OIL 53.88 53.88 215.52
 4 BCC BC CONTIAN 0.15 0.15 0.60
 4 BCO BC OIL LEVY 0.10 0.10 0.40
 PARTS: 1014.31 LABOR: 676.00 OTHER: 1.00 TOTAL LINE A: 1691.31
 97091 replace pressure line replaced pressure line - tested ok -
 cleaned off residue - need new belt - is to oil damaged to use

B REPLCE VENT HOSE FOR FUEL FILTER
 CAUSE: DIAGNOSTIC CHECK UP
 S13 ELECTRICAL / GENERAL DIAGNOSIS
 114 CP 0.00 0.00
 1 220-476-94-26 LINE 66.08 66.08 66.08
 PARTS: 66.08 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 66.08
 97091 replaced vent hose for the fuel filter replaced the vent hose
 for the fuel filter

C** REPLACE ENGINE DRIVE BELT
 CAUSE: DIAGNOSTIC CHECK UP
 S13 ELECTRICAL / GENERAL DIAGNOSIS
 114 CP 169.00 169.00
 1 014-997-37-92LO DRIVE BELT 75.64 75.64 75.64
 PARTS: 75.64 LABOR: 169.00 OTHER: 0.00 TOTAL LINE C: 244.64
 97091 repalce belt replaced belt - tested ok

D** 6 PLUS MERCEDES- BENZ/ SMART LOYALTY PROGRAM - 10% DISCOUNT ON
 PARTS AND LABOUR MY2015 OR OLDER - MB / SMART VEHICLE
 CAUSE: THANK YOU FOR YOUR CONTINUED PATRONAGE
 6+ 6 PLUS MERCEDES- BENZ/ SMART LOYALTY PROGRAM -

THANK- YOU
FOR ALLOWING US
TO SERVICE YOUR VEHICLE!

OUT	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE	DESCRIPTION	TOTALS
	SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.	LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX	
		DATE _____	PLEASE PAY THIS AMOUNT
CUSTOMER SIGNATURE _____			

CUSTOMER #: 56362

86308

Three Point Motors

INVOICE



Mercedes-Benz

2546 Government Street, Victoria, B.C. V8T 4P7
Tel: (250) 385-6737 Fax: (250) 385-2825
www.threepointmotors.com

PAGE 2

VEHICLE #

BU VCV 00

HOME: JUN 1 1:52

BUS:

SERVICE ADVISOR: 90 STEVIE METCALFE

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG	
SIL	06	MERCEDES-BENZ CL600C	WDBPJ76J96A047730	468HHH	97091/97091	T9401	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
16JAN06 IS							
16JAN06 DD	08DEC05	16JAN2010	17:00	30JUN23	169.00	CASH	28JUN23
R.O. OPENED	READY	OPTIONS: DLR:5915 ENG:5.5 Liter					
26JUN23	28JUN23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

10% DISCOUNT ON PARTS AND LABOUR MY2015 OR
 OLDER - MB / SMART VEHICLE
 99 CP

PARTS:	-108.04	LABOR:	-84.50	OTHER:	0.00	TOTAL LINE D:	-192.54
--------	---------	--------	--------	--------	------	---------------	---------

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 49.95

WE AT THREE POINT MOTORS THANK YOU FOR YOUR BUSINESS AND CONTINUED LOYALTY. YOUR SATISFACTION IS EXTREMELY IMPORTANT TO US. YOU WILL RECIEVE A SURVEY FROM MERCEDES-BENZ ABOUT YOUR VISIT. WE ASK THAT YOU FILL THIS OUT AND LET US RESOLVE ANY ISSUES PRIOR TO THE RETURN OF THIS SURVEY. THANK YOU.

GST/HST
PST-1002-9840

(#: 836855122RT0001)

92.98
130.17

**THANK- YOU
 FOR ALLOWING US
 TO SERVICE YOUR VEHICLE!**

OUT

DESCRIPTION	TOTALS
LABOUR AMOUNT	760.50
PARTS AMOUNT	1047.99
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	50.95
TOTAL CHARGES	1859.44
LESS INSURANCE	0.00
SALES TAX	223.15
PLEASE PAY THIS AMOUNT	2082.59

CUSTOMER #: 56362

82919

Three Point Motors

INVOICE



Mercedes-Benz

2546 Government Street, Victoria, B.C. V8T 4P7

Tel: (250) 385-6737 Fax: (250) 385-2825

www.threepointmotors.com

PAGE 1

HOME:

BUS:

SERVICE ADVISOR: 90 STEVIE METCALFE

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
SIL	06	MERCEDES-BENZ CL600C	WDBPJ76J96A047730	468HHH	121693/121696	T6588	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
16JAN06 IS							
16JAN06 DD	08DEC05	16JAN2010	17:00 02MAR23		159.00	CASH	07MAR23
R.O. OPENED		READY	OPTIONS: DLR:5915 ENG:5.5 Liter				
02FEB23		07MAR23					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A C/S: TOW IN- CUSTOMER IS AWARE OF WAIT

ZZZ TELL US MORE

99 CP 0.00 0.00 0.00 0.00 0.00 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

B C/S: CUSTOMER REPORTS- VEHICLE IS NOT STARTING, BATTERY IS NEW, BUT NO STARTING- CHECK AND REPORT

R REPAIR 1.0

701 CP 0.00 159.00 0.00 0.00 0.00 159.00 159.00

PARTS: 0.00 LABOR: 159.00 OTHER: 0.00 TOTAL LINE B: 159.00

DTC scanning performed - found: EZS - Electronic ignition switch B1016 No enable from control module EWM electronic selector lever module. No faults with Electronic selector module found at the moment. DTC memory cleared - the above mentioned fault is still coming on. Recommendation: EZS replacement. Estimated. The selector module operation needs to be checked after replacing the EZS. A DTC protocol printed out.

C * REPLACE EZS + REPAIR WIRING

S12 STD SERV PPM

701 CP 0.00 477.00 0.00 0.00 0.00 477.00 477.00

1 220-545-09-08 EZS SWITCH FBS3 1739.16 1739.16 1739.16

PARTS: 1739.16 LABOR: 477.00 OTHER: 0.00 TOTAL LINE C: 2216.16

Electronic ignition switch replaced. The switch programmed. Checked for proper operation - ok. The engine cranks but it does not start - more time to diagnose is needed [another issue after fixing the starting issue].

D** ADDITIONAL DAIGNOSIS AFTER EIS REPLACEMENT

S12 STD SERV PPM

701 CP 0.00 477.00 0.00 0.00 0.00 477.00 477.00

PARTS: 0.00 LABOR: 477.00 OTHER: 0.00 TOTAL LINE D: 477.00

The vehicle is not starting after replacing the ignition switch [it cranks now but no start], fuel pressure and fuel delivery amount

THANK- YOU
FOR ALLOWING US
TO SERVICE YOUR VEHICLE!

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE

SUM OF \$ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.

DATE CUSTOMER SIGNATURE

DESCRIPTION

LABOUR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES

TOTAL CHARGES

LESS INSURANCE

SALES TAX

PLEASE PAY THIS AMOUNT

TOTALS

CUSTOMER #: 56362

82919

Three Point Motors

INVOICE



Mercedes-Benz

2546 Government Street, Victoria, B.C. V8T 4P7

Tel: (250) 385-8737 Fax: (250) 385-2825

www.threepointmotors.com

PAGE 2

HOME:

BUS:

SERVICE ADVISOR: 90 STEVIE METCALFE

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
SIL	06	MERCEDES-BENZ CL600C	WDBPJ76J96A047730	468HHH	121693/121696	T6588	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
16JAN06 IS							
16JAN06 DD	08DEC05	16JAN2010	17:00 02MAR23		159.00	CASH	07MAR23
R.O. OPENED	READY	OPTIONS: DLR:5915 ENG:5.5 Liter					
02FEB23	07MAR23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

checked - no fuel pressure at all. Battery charger conected, DTC scanning completed - no faults related with engine found. Fuel pump wiring/connection checked - power ok. The fuel pump is inoperative. Recommendation: changing the pump with its relay and fuel filter. Estimated.

E** REPLACE FUEL PUMP WITH RELAY AND FUEL FILTER

S12 STD SERV PPM

701 CP

1 000-982-80-23 RELAY	44.87	44.87	44.87
1 001-470-87-94 FUEL PUMP	739.54	739.54	739.54
1 002-477-61-01 FUEL FILTER	223.46	223.46	223.46
1 BCF FILTER LEVY	0.75	0.75	0.75
1 168-545-58-28 PLUG	9.87	9.87	9.87
2 009-545-81-26 FEMALE CONTACT	6.07	6.07	12.14

PARTS: 1029.88 LABOR: 318.00 OTHER: 0.75 TOTAL LINE E: 1348.63

Fuel pump and relay replaced. During removing of the fuel pump was noticed that the fuel pump connector housing inside is overheated/burnt. It wasn't seen during the previous diagnosis [power to the pump was measured with pin probes]. Additional work estimated.

F** PERFORM WIRING REPAIR AT THE FUEL PUMP

S12 STD SERV PPM

701 CP

PARTS: 0.00 LABOR: 318.00 OTHER: 0.00 TOTAL LINE F: 318.00

Fuel pump wiring harness repaired. Checked for proper operation - ok.

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 39.95

**THANK- YOU
FOR ALLOWING US
TO SERVICE YOUR VEHICLE!**

O
U
T

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE

SUM OF \$ _____
BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE.

DATE _____
CUSTOMER SIGNATURE _____

DESCRIPTION	TOTALS
LABOUR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: 56362

82919

Three Point Motors

INVOICE



Mercedes-Benz

2546 Government Street, Victoria, B.C. V8T 4P7
Tel: (250) 385-6737 Fax: (250) 385-2825
www.threepointmotors.com

PAGE 3

HOME:

BUS:

SERVICE ADVISOR: 90 STEVIE METCALFE

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/ OUT	TAG	
SIL	06	MERCEDES-BENZ CL600C	WDBPJ76J96A047730	468HHH	121693/121696	T6588	
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE
16JAN06 IS							
16JAN06 DD	08DEC05	16JAN2010	17:00 02MAR23		159.00	CASH	07MAR23
R.O. OPENED	READY	OPTIONS: DLR:5915 ENG:5.5 Liter					
02FEB23	07MAR23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
01					CREATED 2023-02-02 08:31:00AM		
02					TAKEN BY JOHANNA BERGINC		

WE AT THREE POINT MOTORS THANK YOU FOR YOUR BUSINESS AND CONTINUED LOYALTY. YOUR SATISFACTION IS EXTREMELY IMPORTANT TO US. YOU WILL RECIEVE A SURVEY FROM MERCEDES-BENZ ABOUT YOUR VISIT. WE ASK THAT YOU FILL THIS OUT AND LET US RESOLVE ANY ISSUES PRIOR TO THE RETURN OF THIS SURVEY. THANK YOU.

GST/HST
PST-1002-9840

(#: 836855122RT0001)

227.90
319.06

**THANK- YOU
FOR ALLOWING US
TO SERVICE YOUR VEHICLE!**

**O
U
T**

INDEBTEDNESS IS HEREBY
ACKNOWLEDGED IN THE

SUM OF \$
BEING ALL OR THE BALANCE
OWING FOR REPAIRS, PARTS
& ACCESSORIES DESCRIBED
IN THIS INVOICE.

DATE _____
CUSTOMER SIGNATURE _____

DESCRIPTION	TOTALS
LABOUR AMOUNT	1749.00
PARTS AMOUNT	2769.04
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	40.70
TOTAL CHARGES	4558.74
LESS INSURANCE	0.00
SALES TAX	546.96
PLEASE PAY THIS AMOUNT	5105.70