



**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

Inspection #1156

**Teri Matthewson**  
 Mobile: (778) 228-4299  
 terimattthewson@hotmail.com

**Vivid Vans Vanagon inspection**

Completed: 06/06/2022

Item	Green	Yellow	Red	N/A
1 Test Drive: Engine smoke? Steering, Suspension feel, Brake feel, Parking Brake feel, Brake Fluid level and condition. Clutch feel, Shift feel, Idling , Power/Acceleration	✓			
<b>Note/Recommendation:</b> <i>Shifts very nice drives good no oddities</i>				
2 Interior: Speedometer	✓			
<b>Note/Recommendation:</b>				
3 Interior: Tachometer				✓
<b>Note/Recommendation:</b>				
4 Interior: Illumination, Climate, Gauges, Cabin, glove box		✓		
<b>Note/Recommendation:</b> <i>Centre gauge light out</i>				
5 Interior: Gauges, Fuel, Temp etc	✓			
<b>Note/Recommendation:</b>				
6 Interior: Front Blower Fan			✓	
<b>Note/Recommendation:</b> <i>Doesn't work</i>				
7 Interior: Rear Blower Fan				✓
<b>Note/Recommendation:</b>				
8 Interior: Heater function Sliders and control valve		✓		
<b>Note/Recommendation:</b> <i>Hot cold lots of resistance likely bad air cooled L or R heater cable</i>				
9 Interior: Vents	✓			
<b>Note/Recommendation:</b>				
10 Interior: switches	✓			




**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

<b>Note/Recommendation:</b>				
11	Interior: Window cranks	✓		
<b>Note/Recommendation:</b>				
12	Interior: mirrors		✓	
<b>Note/Recommendation:</b> <i>Original non power. Feel loose not great visibility</i>				
13	Interior: Glove box	✓		
<b>Note/Recommendation:</b>				
14	Exterior Lights: Headlights; high/Low	✓		
<b>Note/Recommendation:</b>				
15	Exterior Lights: Front markers	✓		
<b>Note/Recommendation:</b>				
16	Exterior Lights: Rear Side Markers			✓
<b>Note/Recommendation:</b> <i>D side out</i>				
17	Exterior Lights: Rear Markers	✓		
<b>Note/Recommendation:</b>				
18	Exterior Lights: Brakes	✓		
<b>Note/Recommendation:</b>				
19	Exterior Lights: Reverse	✓		
<b>Note/Recommendation:</b>				
20	Exterior Lights: Signals	✓		
<b>Note/Recommendation:</b>				
21	Exterior Lights: License plate lights			✓
<b>Note/Recommendation:</b> <i>Both sides out</i>				
22	Exterior: Mirrors	✓		
<b>Note/Recommendation:</b>				
23	Exterior: Wiper Arms	✓		




**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

<b>Note/Recommendation:</b>				
24	Exterior: Doors		✓	
<b>Note/Recommendation:</b> <i>Driver door binds on door seal</i>				
25	Wheels: Weights rating, wear, Pressure	✓		
<b>Note/Recommendation:</b> <i>Laredo. Look ne</i>				
26	Wheels: Spare Tire, condition, Pressure		✓	
<b>Note/Recommendation:</b> <i>Looks extremely old. Highly recommend gett</i>				
27	Front Undercarriage: Upper Control Bushings	✓		
<b>Note/Recommendation:</b>				
28	Front Undercarriage: Wheel bearings	✓		
<b>Note/Recommendation:</b>				
29	Front Undercarriage: Upper Ball joints	✓		
<b>Note/Recommendation:</b> <i>New</i>				
30	Front Undercarriage: Lower Ball Joints		✓	
<b>Note/Recommendation:</b> <i>In bad shape</i>				
				
31	Front Undercarriage: Lower Control Arm Bushings		✓	
<b>Note/Recommendation:</b> <i>Passenger side worn out of spec</i>				
32	Front Undercarriage: Radius Rod Bushings		✓	
<b>Note/Recommendation:</b> <i>Starting to crack</i>				
33	Front Undercarriage: Sway Bar Bushings	✓		



**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

<b>Note/Recommendation:</b>					
34	Front Undercarriage: Tie Rod Ends	✓			
<b>Note/Recommendation:</b>					
35	Front Undercarriage: Steering Rack, Boots, Coupler, Dampner disk	✓			
<b>Note/Recommendation:</b>					
36	Front Undercarriage: Shocks/Springs	✓			
<b>Note/Recommendation:</b>					
37	Front Undercarriage: 2WD Expansion tanks	✓			
<b>Note/Recommendation:</b>					
38	Front Undercarriage: Fuel Tank / Filler / Cap			✓	
<b>Note/Recommendation: Missing clamp</b>					
					
39	Front Undercarriage: Cooling system Leaks, Pipes, Hoses, Clamps				✓
<b>Note/Recommendation:</b>					
40	Front Undercarriage: General Scan of the Area, Rust, wire loom damage etc.	✓			
<b>Note/Recommendation:</b>					
41	BRAKES: Front Calipers, Rotors, Pads, Hoses, Hardlines, Proportioning Valve		✓		
<b>Note/Recommendation: New hardware except for rotors which are not great</b>					
42	Rear Undercarriage: Wheel bearings	✓			




**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

<b>Note/Recommendation:</b>				
43	BRAKES: Rear Drums, Shoes, Wheel Cylinders, Hardware, Hoses, Hardlines and E-Brake Cables	✓		
<b>Note/Recommendation: New</b>				
44	Rear Undercarriage: CV boots	✓		
<b>Note/Recommendation:</b>				
45	Rear Undercarriage: Transmission leaks, Fluid Level, Fluid Condition, Shifter Boots, Shifter Bushings and Mounts			✓
<b>Note/Recommendation: Mount feels bad</b>				
46	Rear Undercarriage: General Scan of the Area, Rust, wire loom damage etc.	✓		
<b>Note/Recommendation:</b>				
47	Rear Undercarriage: Shocks, Springs, Spring Perches and box			✓
<b>Note/Recommendation: Drivers side perch bad. Passenger side in bad shape</b>				
48	Rear Undercarriage: Trailing Arm Bushings	✓		
<b>Note/Recommendation:</b>				
49	Rear Undercarriage: Exhaust			✓
<b>Note/Recommendation: Muffler rusted out</b>				
50	Rear Undercarriage: Cooling system Leaks, Pipes, Hoses, Clamps			✓
<b>Note/Recommendation:</b>				
51	Rear Undercarriage: Lower Engine leaks, oil or Coolant		✓	
<b>Note/Recommendation: Both main seals leaking. No drips on floor after hot but engine very wet</b>				
52	Engine Bay: Belts	✓		
<b>Note/Recommendation:</b>				
53	Engine Bay: Wires/Cap/Rotor/Plugs/Coil	✓		
<b>Note/Recommendation:</b>				
54	Engine Bay: Air Filter	✓		



**Vivid Vans**  
 5301 Chaster Road  
 Unit 602  
 Duncan, BC V9L 0G4  
 (250) 510-6669  
 sales@vividvans.com  
 www.vividvans.com

<b>Note/Recommendation:</b>				
55	Engine Bay: Oil level / Filter	✓		
<b>Note/Recommendation:</b>				
56	Engine Bay: Power Steering			✓
<b>Note/Recommendation:</b>				
57	Engine Bay: <b>**Fuel lines**</b> Junctions, Clamps		✓	
<b>Note/Recommendation: Cracked</b>				
				
58	Engine Bay: Pressure test to 15psi.. Coolant Hoses, Pipes , Junctions, Clamps			✓
<b>Note/Recommendation:</b>				
59	Battery Resting Voltage / Alternator Charging Rate	✓		
<b>Note/Recommendation: 12.6 resting 14.2 charging</b>				
60	windows: excessive scratches/chips/ cracks	✓		
<b>Note/Recommendation: Small scratches seen on each window nothing serious</b>				
<b>Totals</b>		<b>36</b>	<b>8</b>	<b>10</b>
				<b>6</b>