

## **INSPECTION 2 SERVICE**

**Make: BMW**

**Model: E82 128i (N52)**

**Year: 2011**

**Colour: Space Grey (A52)**

**VIN: WBAUP7C5XBVP21443**

**Kilometre Reading: 102,600**

**Date: August 20<sup>th</sup>, 21<sup>st</sup> & 23<sup>rd</sup> 2023.**

**Work Completed By: Owner**

Replaced 2 x Front Shock Absorbers.

Replaced 2 x Front Top Mounts and Gaskets.

Replaced 2 x Front Bump Stops.

Replaced 2 x Front Stabilizer Links.

Replaced Serpentine Belt.

Replaced Serpentine Belt Tensioner.

Replaced Idler Pulley.

Replaced Oil Filter Housing Gasket.

Replaced Air Filter.

Replaced Cabin Filter.

Replaced 6 x Spark Plugs.

Replaced 6 x Ignition Coils.

Replaced Front Brake Discs/Rotors.

Replaced Front Brake Pads.

Replaced Rear Brake Pads.

Replaced Rear Shock Absorbers.

Flushed Rear Diff. Fluid.

Flushed Power Steering Fluid.

Flushed Brake Fluid.

Replaced High-Level Rear Brake Light.

Replaced 2 x Driving Light (ring) Bulbs.

## **INSPECTION 2 SERVICE**

Replaced 2 x Rear Indicator/Signal Bulbs.

Replaced Trunk Bulb.

Replaced Trunk Roundel Badge.

Replaced 2 x Front Footwell Bulbs.

Replaced 2 x Side Indicator/Signal Units

Topped-up Windscreen Washer Fluid.

Topped-up Coolant.

Inspected underbody for damage, leaks, corrosion, etc. – No defects noted.

Inspected engine bay for damage, leaks, corrosion, etc. – No defects noted.

Checked all external lighting – No defects noted.

Checked interior lighting, seat belts, wipers, heater controls, fan, and rear demister – No defects noted.

Undertook test drive – no defects noted.